



**Important!**

**Audi**

Please give copies to  
all your Audi Technicians

# Technical Bulletin

Subject: Engine Oil, Capacities

Group: 17

Number: 99-01

Model(s): A4, A6, A8  
TT

1996 ► 1999  
2000

Date: Mar. 22, 1999

This Bulletin includes new or revised information which will be integrated into the Repair Manual at the next update.

### Engine Oil Capacities:

Vehicle	Engine	Filter change	Capacity
A4	AEB 1.8T	w/filter	3.7 qt / 3.5 L
		w/o filter	3.2 qt / 3.0 L
	AHA 2.8 V6	w/filter	6.3 qt / 6.0 L
		w/o filter	5.8 qt / 5.5 L
A6	AHA 2.8 V6	w/ filter	6.3 qt / 6.0 L
		w/o filter	5.8 qt / 5.5 L
A8	AEW 3.7 V8	w/ filter	8.0 qt / 7.5 L
		w/o filter	7.4 qt / 7.0 L
	ABZ 4.2 V8	w/ filter	8.0 qt / 7.5 L
		w/o filter	7.4 qt / 7.0 L
TT	ATC 1.8 T	w/ filter	4.8 qt / 5.5 L
		w/o filter	4.2 qt / 4.0 L

### Note:

- **DO NOT OVERFILL!** Overfilling engine oil can cause misfire DTC's to be stored in Engine Control Module (ECM) -J220-.
- To prevent overfilling at oil changes, add approx. 1/2 qt less than capacity, start engine, let run until engine operating temperature is approx. 60\_C (140\_F), switch ignition OFF, wait approx. 1 minute, check dipstick, fill to MAX.